

## General Information

Date & Time: 03, Nov, 2025 12:54

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	58,234
<b>Registration No.</b>	NHJ5954	<b>Chassis No.</b>	PA1B18F36P4219526
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	126	108	114
2	Boot Lid	117.3	106	124	122
3	Roof	112.7	113	111	110/117
4	Left Front Fender	107.6	114	106	103
5	Left Front Door	108.6	108	104	114
6	Center Panel Left				
7	Left Rear Door	117.0	128	110	113
8	Left Back Panel	125.3	130	125	121
9	Right Front Fender	108.3	108	110	107
10	Right Front Door	108.6	109	104	113
11	Center Panel Right				
12	Right Rear Door	111.3	106	108	120
13	Right Back Panel	111.3	102	111	121

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>D</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small	<b>Remarks</b> (L) Front Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Roof - Dent - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes

<b>Inspector Notes</b>
with LTO plate/with spare tire/with spare key/with jack and incomplete tools/dome light issue/volume switch issue/No reverse camera/with warranty booklet/possible flooding/plate light issue/abnormal engine noise vibration