

## General Information

Date & Time: 30, Oct, 2025 15:45

<b>Make</b>	Suzuki	<b>Model</b>	Carry
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	5,953
<b>Registration No.</b>	NKN8260	<b>Chassis No.</b>	MHYDC61T9SJ270616
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	120	111	109
2	Boot Lid	152.6	192	128	138
3	Roof	113.0	110	111	109/122
4	Left Front Fender	119.0	116	123	118
5	Left Front Door	107.1	115	107	99
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	154.3	182	134	147
9	Right Front Fender	121.0	114	125	124
10	Right Front Door	114.3	114	118	111
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	135.0	133	129	143

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Ceiling - Grime - Small / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	<b>Remarks</b> (L) Side Gate - Repair mark - Yes / (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Front Panel - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Side Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch & Dent - Small / Rear Gate - Scratch - Medium / (R) Rear Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
With LTO plate and Sparetire and Incomplete Tools, No warranty booklet and Jack, Scratch headlight and tail light, no spare key, no reverse camera, foul smell, worn tires, adhesive marks on vehicle, busted Plate light, busted Room light.