

General Information

Date & Time: 13, Jan, 2025 13:15

Make	Toyota	Model	Vios
YOM	2023	Mileage	6,228
Registration No.	DBI3101	Chassis No.	PA1B18F31P4213326
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	123	108	122
2	Boot Lid	114.3	108	119	116
3	Roof	110.5	123	102	108/109
4	Left Front Fender	93.3	97	97	87
5	Left Front Door	99.9	99	95	106
6	Center Panel Left				
7	Left Rear Door	106.6	113	104	103
8	Left Back Panel	106.3	102	106	111
9	Right Front Fender	106.3	101	101	117
10	Right Front Door	100.8	101	97	105
11	Center Panel Right				
12	Right Rear Door	108.6	105	104	117
13	Right Back Panel	112.0	112	103	121

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks (R) Front Fender, Molding - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch, Peeled - Yes / (L) Rear Fender, Molding - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Step, In-panel, Side Spoiler - Crack, Gap - Medium / (R) Front Door, Molding - Scratch & Dent - Medium
Frame Evaluation : C	Functional Evaluation : B
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no spare tire/ no tools and jack/ no warranty booklet/ with LTO plate/ vehicle running (only low battery) / no reverse camera feature/ broken right headlight and foglight/