


## General Information

Date & Time: 10, Nov, 2025 17:45

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2018	<b>Odo Meter Reading</b>	67,114
<b>Registration No.</b>	GAD1146	<b>Chassis No.</b>	MHKM5EE2FHK008212
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Wagon
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	141.6	151	125	149
2	Boot Lid	138.6	137	143	136
3	Roof	129.5	117	116	143/142
4	Left Front Fender	150.6	163	119	170
5	Left Front Door	120.3	129	125	107
6	Center Panel Left				
7	Left Rear Door	122.0	136	120	110
8	Left Back Panel	121.3	140	117	107
9	Right Front Fender	115.3	123	112	111
10	Right Front Door	139.6	139	149	131
11	Center Panel Right				
12	Right Rear Door	129.3	120	137	131
13	Right Back Panel	162.6	225	122	141

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Rear Trim - Grime - Small / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> (R) Rear Fender - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Crack, Gap - Medium / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / (R) Front Fender, Molding - Scratch - Small / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>yellow marks at headlight. Radiator leak. Retractable mirror switch issue. Without warranty booklet,jack,tools and seat cover. With spare tire. 1 key. With LTO plate.</p>