

General Information

Date & Time: 17, Nov, 2025 18:57

Make	Toyota	Model	Hiace
YOM	2024	Odo Meter Reading	28,308
Registration No.	JAS7066	Chassis No.	JTFJT02P0R0018427
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	81.7	83	79	83
2	Boot Lid	66.0	70	69	59
3	Roof	73.3	70	79	71/73
4	Left Front Fender	82.3	85	77	85
5	Left Front Door	76.0	73	80	74
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	79.4	90	73	75
9	Right Front Fender	83.3	86	79	85
10	Right Front Door	74.1	75	76	72
11	Center Panel Right	74.3	80	72	71
12	Right Rear Door	81.5	79	82	84
13	Right Back Panel	76.8	81	76	74

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Trim - Cut, Crack - Minimal</p>	<p>Remarks (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Front Windshield - Scratch, Stone chip - Medium / Roof - Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light,</p>