

## General Information

Date & Time: 18, Nov, 2025 19:46

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	28,606
<b>Registration No.</b>	GBD8048	<b>Chassis No.</b>	PA1B18F38R4270514
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	118	108	113
2	Boot Lid	110.3	102	110	119
3	Roof	101.1	99	109	98/98
4	Left Front Fender	96.8	88	109	93
5	Left Front Door	99.5	99	100	100
6	Center Panel Left				
7	Left Rear Door	103.5	107	105	99
8	Left Back Panel	110.6	118	108	106
9	Right Front Fender	100.6	103	98	101
10	Right Front Door	95.7	96	97	94
11	Center Panel Right				
12	Right Rear Door	101.9	105	96	105
13	Right Back Panel	104.6	96	97	121

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>E</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Trunk Room - Worked - Large / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / Mat Other - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Grime - Small / Glove Box - Worn, Scratch, Cut, Crack - Minimal	<b>Remarks</b> Member (Bolted) - Dent - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Crack, Gap - Medium / Roof - Scratch - Small
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
no warranty booklet, no jack and tools, with spare tire, no LTO plate, scratches on tail light, trunk floor cover missing