

General Information

Date & Time: 13, Nov, 2025 15:46

Make	Hino	Model	XZU710LN
YOM	2024	Odo Meter Reading	28,499
Registration No.	NKF7544	Chassis No.	JHHUCP3F3RK056398
CC	4.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Aluminum Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	65.6	64	71	62
2	Boot Lid	16.3	16	17	16
3	Roof	63.0	74	69	17/92
4	Left Front Fender				
5	Left Front Door	78.2	71	72	92
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	16.3	17	16	16
9	Right Front Fender				
10	Right Front Door	72.1	69	73	74
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	14.5	15	16	13

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes</p>	<p>Remarks (L) Side Gate - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / Front Panel - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Roof - Scratch & Dent - Small / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Cab Back Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, No spare key, no reverse camera, scratch headlight and tail light, Worn Tires, foul smell, adhesive marks on vehicle.</p>