

General Information

Date & Time: 12, Nov, 2025 15:39

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	1,406
Registration No.	CDA4662	Chassis No.	PAHAWAAA0S1340378
CC	2.0	Transmission	M/T
Fuel Type	Gas	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	98	109	100
2	Boot Lid	61.3	75	52	57
3	Roof	117.2	122	118	119/110
4	Left Front Fender	100.9	106	104	93
5	Left Front Door	92.5	93	95	90
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	75.3	78	76	72
9	Right Front Fender	99.8	94	100	106
10	Right Front Door	99.5	97	100	102
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	75.6	76	74	77

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Small / (R) Rear Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Small / Cab Back Panel - Scratch - Small / Cargo Bed Floor - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

With LTO plate and Sparetire and Jack and Tools, No warranty booklet, scratch headlight and tail light.