

## General Information

Date & Time: 13, Nov, 2025 08:52

<b>Make</b>	Toyota	<b>Model</b>	Lite Ace
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	12,085
<b>Registration No.</b>	CCJ7226	<b>Chassis No.</b>	MHKU3FE10K010271
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Utility Passenger
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	59.9	58	68	54
2	Boot Lid	80.1	83	53	104
3	Roof	60.0	48	67	59/67
4	Left Front Fender	64.7	72	56	67
5	Left Front Door	61.6	69	61	55
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	75.1	60	84	82
9	Right Front Fender	67.7	74	56	74
10	Right Front Door	58.8	52	59	66
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	63.5	65	59	66

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Ceiling - Grime - Medium	<b>Remarks</b> (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Crack, Gap - Large / (L) Side Gate - Scratch - Medium / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Cab Back Panel - Scratch & Dent - Medium / (R) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
With Lto plate, with warranty booklet, 1key, with spare tire, no jack and tools, wheel cover rear right missing