

General Information

Date & Time: 13, Nov, 2025 15:45

Make	Hino	Model	XZU710LN
YOM	2022	Odo Meter Reading	128,125
Registration No.	NIF9131	Chassis No.	JHHUCP3F3MK043384
CC	4.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Aluminum Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	65.0	64	63	69
2	Boot Lid	17.7	17	17	19
3	Roof	57.9	64	68	17/83
4	Left Front Fender				
5	Left Front Door	77.3	71	71	90
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	18.2	17	16	21
9	Right Front Fender				
10	Right Front Door	148.3	100	113	232
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	16.8	13	20	17

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Ceiling - Grime - Large / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (L) Front Seat - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small / Steering Wheel - Worn, Peel, Crack - Medium / (R) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Loose, Deformed - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (R) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (R) Front Fender, Molding - Partially Missing - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Front Panel - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Medium / Front Windshield - Scratch, Stone chip - Medium / (R) Side Gate - Scratch & Dent - Large / Roof - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Dent - Medium / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal</p>
Frame Evaluation : D	Functional Evaluation : E
<p>Remarks Right Front Pillar - Condition of Welding ? - Yes</p>	<p>Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Door Lock - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate rear missing front LTO plate, missing front bumper, missing right headlight and right side mirror, no reverse camera, No spare key, worn tires and Sparetire, No Tools and Jack and Warranty booklet, scratch and crack tail light and headlight, foul smell, possible flooded, warning lamps on, Aircon weak, horn issue, rear bumper missing.</p>