

General Information

Date & Time: 13, Jan, 2025 12:13

Make	Toyota	Model	Vios
YOM	2023	Mileage	23,767
Registration No.	DBH5967	Chassis No.	PA1B18F31P4207574
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.2	99	100	108
2	Boot Lid	98.6	97	96	103
3	Roof	97.5	109	91	96/94
4	Left Front Fender	88.0	92	86	86
5	Left Front Door	85.4	83	87	87
6	Center Panel Left				
7	Left Rear Door	98.3	101	99	95
8	Left Back Panel	99.3	105	98	95
9	Right Front Fender	82.3	83	80	84
10	Right Front Door	85.4	86	85	85
11	Center Panel Right				
12	Right Rear Door	88.4	85	88	93
13	Right Back Panel	94.4	95	93	95

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium	Remarks (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Wheel, Cover - Cap Missing - Yes / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
without tools and warranty booklet.