

General Information

Date & Time: 17, Nov, 2025 18:52

Make	MG	Model	HS
YOM	2022	Odo Meter Reading	28,354
Registration No.	NEE8067	Chassis No.	LSJA24UXNN099661
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	193.3	183	204	193
2	Boot Lid	116.0	124	118	106
3	Roof	125.5	117	113	138/134
4	Left Front Fender	112.6	111	116	111
5	Left Front Door	118.0	117	123	114
6	Center Panel Left				
7	Left Rear Door	169.6	158	177	174
8	Left Back Panel	179.3	185	171	182
9	Right Front Fender	159.0	147	147	183
10	Right Front Door	116.6	116	112	122
11	Center Panel Right				
12	Right Rear Door	125.0	138	115	122
13	Right Back Panel	187.0	159	192	210

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Small	Remarks Bonnet - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Crack - Cracks / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes

Inspector Notes

With Lto plate, with warranty booklet, with jack and spare tire, 2keys, tools, scratches on headlight