

## General Information

Date & Time: 19, Nov, 2025 11:04

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	9,506
<b>Registration No.</b>	DBT8664	<b>Chassis No.</b>	PAHACACA3S6423537
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Utility Passenger
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	143	103	110
2	Boot Lid	74.8	69	64	91
3	Roof	112.5	112	114	121/103
4	Left Front Fender	104.5	109	108	97
5	Left Front Door	97.4	101	98	93
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	63.1	66	63	60
9	Right Front Fender	104.0	102	107	103
10	Right Front Door	100.3	89	98	114
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	69.4	77	60	71

**Overall Evaluation :**

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal</p>	<p><b>Remarks</b>  Cargo Bed Floor - Scratch &amp; Dent - Large / Roof - Dent - Medium / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch &amp; Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Guard Frame - Scratch &amp; Dent - Minimal / (R) Guard Frame - Scratch &amp; Dent - Minimal / Rear Gate - Scratch - Minimal / Cab Back Panel - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<b>Inspector Notes</b>
<p>with LTO plate, with manual &amp; warranty booklet, no reverse camera, no tools &amp; jack, scratches on taillight.</p>