

General Information

Date & Time: 21, Nov, 2025 08:58

Make	Toyota	Model	Hilux
YOM	2015	Odo Meter Reading	285,602
Registration No.	ABT9562	Chassis No.	MR0HA8CD201050164
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	308.0	311	307	306
2	Boot Lid	371.3	395	361	358
3	Roof	240.0	241	239	278/202
4	Left Front Fender	312.0	318	313	305
5	Left Front Door	266.3	280	255	264
6	Center Panel Left				
7	Left Rear Door	362.3	589	249	249
8	Left Back Panel	301.3	259	358	287
9	Right Front Fender	245.3	264	242	230
10	Right Front Door	347.3	464	284	294
11	Center Panel Right				
12	Right Rear Door	314.3	328	257	358
13	Right Back Panel	319.6	292	322	345

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small / (L) Rear Trim - Grime - Minimal / (R) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Rear Door, Molding - Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Side Gate - Scratch - Small / (L) Rear Corner Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Cab Back Panel - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Different Grille, front bumper, headlight and taillight. Gap and partially missing at rear bumper. Rear view mirror detached at the front windshield. Interior lights issue. Scratches at headlight and taillight. With warranty booklet, spare tire and seat cover. Without jack and tools. 1 key. With LTO plate.