

## General Information

Date & Time: 24, Nov, 2025 14:48

<b>Make</b>	Suzuki	<b>Model</b>	Carry
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	16,239
<b>Registration No.</b>	NHF6693	<b>Chassis No.</b>	MHYDC61T1PJ214824
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Dropside
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	120	107	124
2	Boot Lid	97.7	96	104	94
3	Roof	94.5	110	102	85/81
4	Left Front Fender	121.6	118	127	120
5	Left Front Door	108.3	100	116	109
6	Center Panel Left	121.0	110	124	129
7	Left Rear Door	104.6	111	100	103
8	Left Back Panel	100.2	103	98	100
9	Right Front Fender	118.6	119	120	117
10	Right Front Door	105.2	110	112	94
11	Center Panel Right	110.6	111	117	104
12	Right Rear Door	108.6	105	107	114
13	Right Back Panel	109.3	106	115	107

**Overall Evaluation :**

C

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Large / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small</p>	<p><b>Remarks</b> (L) Side Gate - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Small / (R) Side Gate - Dent - Medium / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / Cargo Bed Floor - Scratch - Medium / Roof - Dent - Large / Bonnet, Headlight - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/No spare key/No jack and tools/with warranty booklet/No reverse camera/No fog light/headlights issue/No horn /head unit issue/audio radio issue</p>