

## General Information

Date & Time: 26, Nov, 2025 12:36

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	20,979
<b>Registration No.</b>	NEY9702	<b>Chassis No.</b>	PA1B18F32R4265387
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	113	107	109
2	Boot Lid	125.3	94	106	176
3	Roof	99.8	102	101	91/105
4	Left Front Fender	98.9	103	98	96
5	Left Front Door	104.0	100	102	110
6	Center Panel Left				
7	Left Rear Door	109.0	113	110	104
8	Left Back Panel	111.3	117	115	102
9	Right Front Fender	113.6	102	108	131
10	Right Front Door	97.2	98	99	95
11	Center Panel Right				
12	Right Rear Door	97.2	98	96	98
13	Right Back Panel	103.9	107	97	108

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em;">B</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Large / Carpet - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Cut, Crack - Small / (R) Front Seat - Grime - Minimal / Ceiling - Grime - Small / Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal</p>	<p><b>Remarks</b> Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
no warranty booklet, jack, no tools, with spare tire, with LTO plate, scratches on tail light