

## General Information

Date & Time: 16, Feb, 2026 15:27

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2020	<b>Odo Meter Reading</b>	75,902
<b>Registration No.</b>	NFV6414	<b>Chassis No.</b>	PA1B18F37L4112429
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Green		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	108	108	107
2	Boot Lid	105.1	105	97	114
3	Roof	87.4	96	83	85/85
4	Left Front Fender	92.4	91	94	92
5	Left Front Door	116.6	108	120	122
6	Center Panel Left				
7	Left Rear Door	121.0	127	119	117
8	Left Back Panel	132.6	133	130	135
9	Right Front Fender	93.8	96	92	93
10	Right Front Door	94.3	91	95	97
11	Center Panel Right				
12	Right Rear Door	96.5	98	94	98
13	Right Back Panel	97.1	94	96	101

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em;">D</span>
	
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>            Console, Switches, Vents - Loose, Deformed - Small / (L)            Front Trim - Grime - Minimal</p>	<p><b>Remarks</b>            (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Roof - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em;">C</span>
<p><b>Remarks</b>            Defects not found</p>	<p><b>Remarks</b>            Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
<p>Issue on Lto plate-Change plate,with jack, 1key, no warranty booklet and tools, no spare tire, scratches on headlights and taillights, door knob cover missing, fender light issue,battery weak, aircon issue</p>