

General Information

Date & Time: 14, Jan, 2026 15:56

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	38,250
Registration No.	NFS9035	Chassis No.	PA1B18F36R4243313
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	108	107	101
2	Boot Lid	108.3	112	103	110
3	Roof	94.1	93	94	91/99
4	Left Front Fender	94.9	95	93	97
5	Left Front Door	100.2	96	108	97
6	Center Panel Left				
7	Left Rear Door	99.4	100	99	99
8	Left Back Panel	107.6	120	100	103
9	Right Front Fender	103.3	107	101	102
10	Right Front Door	103.0	105	100	104
11	Center Panel Right				
12	Right Rear Door	104.6	103	106	105
13	Right Back Panel	109.6	106	108	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Defects not found</p>	<p>Remarks (R) Step - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large</p>
Frame Evaluation : B	Functional Evaluation : B
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with spare tire, with jack, 1key, no tools, no warranty booklet, front underhood cover missing, cover under the engine missing, scratches on headlight and taillight</p>