


General Information

Date & Time: 05, Dec, 2025 13:03

Make	Mitsubishi	Model	Montero SPT
YOM	2014	Odo Meter Reading	105,844
Registration No.	WQX758	Chassis No.	MMBGRKG40ED006320
CC	2.5	Transmission	A/T
Fuel Type	Diesel	Type of Body	Sport Utility
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	75.8	75	80	73
2	Boot Lid	126.3	118	125	136
3	Roof	83.7	74	69	117/75
4	Left Front Fender	87.1	91	82	89
5	Left Front Door	78.3	76	77	82
6	Center Panel Left				
7	Left Rear Door	76.0	83	76	69
8	Left Back Panel	140.6	94	107	221
9	Right Front Fender	78.5	78	77	81
10	Right Front Door	71.6	72	70	73
11	Center Panel Right				
12	Right Rear Door	74.6	71	72	81
13	Right Back Panel	79.4	76	73	90

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
	
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Overall Exterior - Faded(Color, Gloss) - Yes / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Air Conditioner - Function - Weak / Power Steering Pump - Leak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>Sunglass holder issue. Radio issue. Aircon issue. Left reverse light busted. Without warranty booklet, jack and tools. With spare tire and seat cover. 1 key. With LTO plate.</p>