

General Information

Date & Time: 03, Dec, 2025 14:54

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	62,080
Registration No.	NHR5228	Chassis No.	MHKU3FE10PK005173
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.8	118	65	56
2	Boot Lid	82.3	75	60	112
3	Roof	54.1	46	68	50/53
4	Left Front Fender	60.0	60	55	65
5	Left Front Door	61.7	69	59	58
6	Center Panel Left	65.7	71	57	70
7	Left Rear Door				
8	Left Back Panel	99.6	79	137	84
9	Right Front Fender	65.0	72	60	63
10	Right Front Door	57.6	60	58	55
11	Center Panel Right	63.7	62	66	63
12	Right Rear Door				
13	Right Back Panel	95.5	68	108	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Cut, Crack - Medium / Rear Seat - Missing - Yes / (R) Front Trim - Cut, Crack - Medium / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (L) Front Trim - Cut, Crack - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / Front Windshield - Scratch, Stone chip - Large / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Cargo Bed Floor - Scratch & Dent - Large / Cab Back Panel - Scratch & Dent - Large / Rear Gate - Scratch - Large / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Front Panel - Scratch & Dent - Medium / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, no spare tire, with LTO plate, scratches on headlight,</p>