

## General Information

Date & Time: 01, Dec, 2025 15:48

<b>Make</b>	Toyota	<b>Model</b>	Corolla Cross
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	22,381
<b>Registration No.</b>	NOW4421	<b>Chassis No.</b>	MR2KZAAG0P0079575
<b>CC</b>	1.8	<b>Transmission</b>	HEV CVT
<b>Fuel Type</b>	Hybrid	<b>Type of Body</b>	SUV
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	163.0	163	166	160
2	Boot Lid	142.3	146	141	140
3	Roof	132.5	168	137	115/110
4	Left Front Fender	160.3	158	165	158
5	Left Front Door	161.6	167	160	158
6	Center Panel Left				
7	Left Rear Door	166.3	168	164	167
8	Left Back Panel	159.3	161	157	160
9	Right Front Fender	163.6	163	164	164
10	Right Front Door	164.6	169	163	162
11	Center Panel Right				
12	Right Rear Door	161.6	161	158	166
13	Right Back Panel	154.3	146	153	164

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>A</b>	<b>Exterior Evaluation :</b>	<b>C</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Floor Mat - Worked - Small / Steering Wheel - Worn, Peel, Crack - Small / (R) Front Floor Mat - Grime - Small</p>		<p><b>Remarks</b> (R) Step - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
With LTO plate and Sparetire and Jack and Incomplete Tools, with warranty booklet, scratch headlight and tail light, Worn Tires.