

## General Information

Date & Time: 09, Dec, 2025 15:17

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	31,778
<b>Registration No.</b>	NFJ2868	<b>Chassis No.</b>	JTFJT02P8M0015154
<b>CC</b>	3.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	76.0	77	76	75
2	Boot Lid	74.6	74	79	71
3	Roof	75.0	66	82	77/76
4	Left Front Fender	81.8	73	82	90
5	Left Front Door	75.9	70	78	80
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	72.2	77	70	70
9	Right Front Fender	74.8	76	74	75
10	Right Front Door	74.4	76	70	77
11	Center Panel Right	86.2	89	96	74
12	Right Rear Door	105.9	147	96	75
13	Right Back Panel	134.0	114	137	151

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>C</b>	<b>Exterior Evaluation :</b>	<b>E</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes / (L) Front Trim - Worked - Small / Ceiling - Grime - Small / Display, Audio System - Missing - Yes / (R) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes</p>		<p><b>Remarks</b> (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Mirror - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Center Panel - Scratch &amp; Dent - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Front Panel - Scratch - Small / Roof - Scratch - Medium</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>	

<b>Inspector Notes</b>
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light, head unit missing, dome light issue