

## General Information

Date & Time: 09, Dec, 2025 10:16

<b>Make</b>	Toyota	<b>Model</b>	Veloz
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	18,378
<b>Registration No.</b>	NHM7470	<b>Chassis No.</b>	MHFAB1BY2P3072774
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.7	97	100	108
2	Boot Lid	95.0	91	106	88
3	Roof	118.5	121	116	131/106
4	Left Front Fender	93.0	94	93	93
5	Left Front Door	114.0	102	115	125
6	Center Panel Left				
7	Left Rear Door	117.3	116	103	133
8	Left Back Panel	112.1	132	93	111
9	Right Front Fender	90.3	90	90	91
10	Right Front Door	114.0	119	114	109
11	Center Panel Right				
12	Right Rear Door	114.6	125	108	111
13	Right Back Panel	119.6	118	109	132

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b> Bonnet, Headlight - Dent - Small / (L) Front Door, Molding - Dent - Small / Roof - Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Crack, Gap - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Crack, Gap - Medium / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/No spare key/with jack and incomplete tools/with reverse camera/No warranty booklets/interior dirty</p>