

## General Information

Date & Time: 10, Dec, 2025 16:30

<b>Make</b>	Toyota	<b>Model</b>	Lite Ace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	8,809
<b>Registration No.</b>	NFS2302	<b>Chassis No.</b>	MHKU3FE10PK005312
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	61.5	58	65	62
2	Boot Lid	95.0	132	63	90
3	Roof	56.4	49	73	48/57
4	Left Front Fender	62.1	61	60	65
5	Left Front Door	62.6	71	63	55
6	Center Panel Left	57.9	64	52	58
7	Left Rear Door	95.0	113	83	89
8	Left Back Panel	116.0	117	123	108
9	Right Front Fender	68.5	79	63	64
10	Right Front Door	62.5	55	63	70
11	Center Panel Right	62.1	65	55	67
12	Right Rear Door	117.0	108	113	130
13	Right Back Panel	117.3	112	111	129

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Large / (L) Front Trim - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b> Front Bumper, Grille, Lamps - Scratch - Large / (L) Side Gate - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Cargo Bed Floor - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Front Panel - Scratch - Small / Roof - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Side Gate - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet/with LTO plate/with jack and tools/No reverse camera/with spare tire /with spare key</p>