

## General Information

Date & Time: 15, Jan, 2026 05:52

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	4,459
<b>Registration No.</b>	FAT4031	<b>Chassis No.</b>	PAHAD9DAS1627721
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Dropside
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.7	96	97	92
2	Boot Lid	75.8	78	74	75
3	Roof	107.0	113	102	100/113
4	Left Front Fender	102.0	101	104	101
5	Left Front Door	95.8	99	98	91
6	Center Panel Left	87.9	88	105	71
7	Left Rear Door	81.5	89	79	76
8	Left Back Panel	74.2	85	68	71
9	Right Front Fender	107.3	107	116	99
10	Right Front Door	101.3	100	101	103
11	Center Panel Right	97.5	96	99	98
12	Right Rear Door	69.3	69	67	73
13	Right Back Panel	74.2	74	72	77

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b> (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Guard Frame - Scratch - Medium / Cargo Bed Floor - Scratch - Large / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Guard Frame - Scratch - Large / (R) Rear Corner Panel - Scratch - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch &amp; Dent - Medium / Roof - Scratch - Small / Rear Windshield - Scratch, Stone chip - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/No spare key/No reverse camera/with jack and jack/No fog light/No warranty booklet</p>