

General Information

Date & Time: 19, Jan, 2026 08:29

Make	Mitsubishi	Model	L300
YOM	2024	Odo Meter Reading	71,953
Registration No.	CCC2015	Chassis No.	PAEL65MYRPB013653
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	65.4	65	63	68
2	Boot Lid	122.1	74	213	79
3	Roof	68.6	67	69	73/66
4	Left Front Fender	85.3	92	79	85
5	Left Front Door	66.8	70	65	66
6	Center Panel Left	72.8	74	72	73
7	Left Rear Door				
8	Left Back Panel	262.6	139	330	319
9	Right Front Fender	72.1	74	72	70
10	Right Front Door	285.6	617	120	120
11	Center Panel Right	111.6	73	126	136
12	Right Rear Door				
13	Right Back Panel	85.4	83	81	93

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Console, Switches, Vents - Loose, Deformed - Small / Overall Interior - Worn as per age - Yes / (L) Front Trim - Loose, Deformed - Medium / Ceiling - Grime - Small</p>		<p>Remarks (R) Front Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch & Dent - Small / (R) Side Gate - Rust, Corrosion - Large / (L) Side Gate - Rust, Corrosion - Large / Cargo Bed Floor - Rust, Corrosion - Large / Cab Back Panel - Rust, Corrosion - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Rear Gate - Rust, Corrosion - Large / (L) Center Panel - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Front Panel - Scratch & Dent - Large / Roof - Dent - Large</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Air Conditioner - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes</p>	

Inspector Notes
with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light, dome light issue, air-conditioning system issue,