

## General Information

Date & Time: 15, Dec, 2025 15:49

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	22,198
<b>Registration No.</b>	CCF2270	<b>Chassis No.</b>	JTFNAFAPXR8043154
<b>CC</b>	2.8	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.5	102	92	99
2	Boot Lid	130.3	118	138	135
3	Roof	107.7	121	107	103/100
4	Left Front Fender	94.1	94	100	88
5	Left Front Door	99.1	104	98	95
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	94.2	95	92	96
9	Right Front Fender	99.6	110	94	95
10	Right Front Door	93.6	91	93	96
11	Center Panel Right				
12	Right Rear Door	102.6	101	100	107
13	Right Back Panel	102.6	107	101	100

Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Worked - Small / Mat Other - Missing - Yes / Dashboard - Traces of Adhesive Tape - Yes / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Overall Interior - Smell - Yes / Ceiling - Grime - Small</p>	<p><b>Remarks</b> (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With LTO plate and Sparetire and Jack and Incomplete Tools, No Spare key, Scratch and Crack Tail light and Headlight, worn tires, foul smell, plate light issue and room light issue,air-conditioned issue.</p>