

General Information

Date & Time: 20, Dec, 2025 15:11

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	32,758
Registration No.	NFM8926	Chassis No.	PAEL65MYSRB024737
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	78.5	84	75	77
2	Boot Lid	72.0	84	64	68
3	Roof	79.3	57	126	70/64
4	Left Front Fender	86.6	83	98	80
5	Left Front Door	68.4	71	66	68
6	Center Panel Left	84.0	75	104	73
7	Left Rear Door	68.0	68	70	66
8	Left Back Panel	89.1	86	98	84
9	Right Front Fender	79.6	70	86	82
10	Right Front Door	66.9	72	62	67
11	Center Panel Right	76.1	76	76	77
12	Right Rear Door	70.5	74	63	74
13	Right Back Panel	71.9	81	60	75

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Large / Rear Seat - Cut, Crack - Large / Ceiling - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small</p>		<p>Remarks (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Center Panel - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / (R) Side Gate - Scratch - Large / Rear Gate - Scratch - Large / (R) Center Panel - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / Front Panel - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / Roof - Scratch & Dent - Small / Cargo Bed Floor - Crack, Gap - Large / Rear Windshield - Scratch, Stone chip - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Seat Belts - Issue - Yes</p>	

Inspector Notes
with LTO plate/with spare tire/with 1 spare key/No jack and tools/No reverse camera/No warranty booklet/No fog light