

## General Information

Date & Time: 06, Jan, 2026 10:00

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	5,847
<b>Registration No.</b>	NHH2432	<b>Chassis No.</b>	PAEL65NYSSB001157
<b>CC</b>	2.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.1	80	82	79
2	Boot Lid	85.0	86	90	79
3	Roof	83.0	59	138	69/67
4	Left Front Fender	101.7	153	79	74
5	Left Front Door	67.1	69	66	67
6	Center Panel Left	76.0	79	75	73
7	Left Rear Door				
8	Left Back Panel	171.3	113	113	288
9	Right Front Fender	82.8	77	87	85
10	Right Front Door	65.9	66	69	63
11	Center Panel Right	84.7	87	83	84
12	Right Rear Door				
13	Right Back Panel	183.3	246	180	124

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Ceiling - Grime - Small	<b>Remarks</b> (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / Rear Gate - Scratch - Minimal / Rear Gate - Modified - Small / (L) Side Gate - Scratch & Dent - Medium / (L) Center Panel - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Front Panel - Scratch - Minimal
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes

<b>Inspector Notes</b>
with warranty booklet, no jack, with tools, with spare tire, with LTO plate