

General Information

Date & Time: 15, Dec, 2025 10:26

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	18,143
Registration No.	NKG3351	Chassis No.	PAEL65MYSRB025362
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.7	78	83	129
2	Boot Lid	64.6	56	71	67
3	Roof	141.9	71	63	327/107
4	Left Front Fender	80.0	78	84	78
5	Left Front Door	72.0	69	69	79
6	Center Panel Left	80.1	76	83	81
7	Left Rear Door				
8	Left Back Panel	159.7	113	294	72
9	Right Front Fender	76.2	83	70	75
10	Right Front Door	75.2	91	64	71
11	Center Panel Right	80.3	82	79	79
12	Right Rear Door				
13	Right Back Panel	117.3	95	137	120

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Side Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Cargo Bed Floor - Scratch - Large / (R) Side Gate - Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Rear Gate - Repair mark - Yes / Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no tools/ radio issue/ with warranty booklet and LTO plate/ with jack and spare tire/</p>