

General Information

Date & Time: 15, Dec, 2025 10:28

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	16,786
Registration No.	NKH4871	Chassis No.	PAEL65MYSRB026861
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	76.8	87	75	68
2	Boot Lid	76.4	70	87	73
3	Roof	69.4	68	67	75/68
4	Left Front Fender	77.7	77	80	76
5	Left Front Door	69.0	64	68	75
6	Center Panel Left	70.3	69	68	75
7	Left Rear Door				
8	Left Back Panel	99.3	99	112	87
9	Right Front Fender	66.7	72	64	64
10	Right Front Door	65.7	67	63	67
11	Center Panel Right	76.7	73	81	77
12	Right Rear Door				
13	Right Back Panel	88.3	73	106	86

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Carpet - Worn, Scratch, Cut, Crack - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Switchs - Missing - Yes	Remarks (R) Side Gate - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Medium / Front Panel - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Large / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Cargo Bed Floor - Scratch - Large / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes

Inspector Notes
no jack and tools/ no spare tire/weak air-conditioning/with warranty booklet and LTO plate