

General Information

Date & Time: 15, Dec, 2025 10:29

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	16,443
Registration No.	NKL9508	Chassis No.	PAEL65MYSRB027928
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	78.0	72	77	85
2	Boot Lid	74.8	98	60	67
3	Roof	79.8	60	84	68/107
4	Left Front Fender	74.0	75	77	71
5	Left Front Door	63.6	69	60	63
6	Center Panel Left	70.1	69	69	72
7	Left Rear Door				
8	Left Back Panel	89.4	86	114	68
9	Right Front Fender	74.8	83	80	61
10	Right Front Door	62.3	65	60	62
11	Center Panel Right	78.9	80	75	82
12	Right Rear Door				
13	Right Back Panel	75.7	60	78	89

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Dashboard - Loose, Deformed - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Side Gate - Dent - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / (L) Side Gate - Scratch & Dent - Medium / Front Panel - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Cargo Bed Floor - Scratch - Large / Roof - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no spare tire/ with warranty booklet and LTO plate/ with jack and tools</p>