

## General Information

Date & Time: 13, Jan, 2026 08:24

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	14,428
<b>Registration No.</b>	NKH3738	<b>Chassis No.</b>	PAEL65MYSRB026527
<b>CC</b>	2.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	83.6	82	82	87
2	Boot Lid	90.1	104	84	83
3	Roof	80.5	104	75	73/71
4	Left Front Fender	86.9	87	83	92
5	Left Front Door	67.1	70	67	65
6	Center Panel Left	79.1	79	78	80
7	Left Rear Door				
8	Left Back Panel	101.9	119	77	110
9	Right Front Fender	87.9	74	109	80
10	Right Front Door	61.7	66	57	62
11	Center Panel Right	75.8	74	77	77
12	Right Rear Door				
13	Right Back Panel	94.9	87	98	100

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Small / Display, Audio System - Missing - Yes</p>	<p><b>Remarks</b>          (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Panel - Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / (L) Center Panel - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Side Gate - Scratch &amp; Dent - Small / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Small / Cargo Bed Floor - Scratch &amp; Dent - Medium / (R) Center Panel - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Medium / Roof - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate ,with spare tire, with spare key, with jack, no tools, no warranty and manual booklet, no reverse camera, scratches on taillight, window right side issue.</p>