


## General Information

Date & Time: 22, Dec, 2025 10:52

<b>Make</b>	Mitsubishi	<b>Model</b>	Montero SPT
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	6,556
<b>Registration No.</b>	CCK1486	<b>Chassis No.</b>	MMBGJKR10SH00312
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	131	113	119
2	Boot Lid	124.6	130	118	126
3	Roof	113.0	121	121	107/103
4	Left Front Fender	111.3	121	104	109
5	Left Front Door	109.3	115	108	105
6	Center Panel Left				
7	Left Rear Door	104.7	102	97	115
8	Left Back Panel	118.3	118	125	112
9	Right Front Fender	122.0	113	125	128
10	Right Front Door	114.3	113	118	112
11	Center Panel Right				
12	Right Rear Door	108.3	108	112	105
13	Right Back Panel	113.0	123	116	100

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Mat Other - Missing - Yes	<b>Remarks</b> Front Bumper, Grille, Lamps - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Small
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>
with tools and spare tire/ with jack/ with LTO plate and warranty booklet/