

## General Information

Date & Time: 09, Jan, 2026 15:06

<b>Make</b>	MG	<b>Model</b>	MG 5
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	2,531
<b>Registration No.</b>	NHU5914	<b>Chassis No.</b>	LSJA36E37RZ175581
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	146.3	152	137	150
2	Boot Lid	134.3	131	140	132
3	Roof	122.5	114	131	124/121
4	Left Front Fender	124.0	128	107	137
5	Left Front Door	142.6	146	147	135
6	Center Panel Left				
7	Left Rear Door	130.0	127	137	126
8	Left Back Panel	141.3	148	126	150
9	Right Front Fender	133.0	134	125	140
10	Right Front Door	144.6	146	144	144
11	Center Panel Right				
12	Right Rear Door	132.0	135	131	130
13	Right Back Panel	141.0	143	136	144

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / Rear Seat - Grime - Minimal / (R) Front Seat - Grime - Small</p>	<p><b>Remarks</b> (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Overall Exterior - Worn as per age - Yes / Roof - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet, jack and tools, with spare tire, no LTO plate, scratches on tail light and headlight, reverse light issue,</p>