

General Information

Date & Time: 20, Dec, 2025 15:15

Make	Toyota	Model	Avanza
YOM	2023	Odo Meter Reading	39,857
Registration No.	DBI1964	Chassis No.	MHFAB1BY5P3062076
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.2	100	100	101
2	Boot Lid				
3	Roof	112.5	110	114	119/107
4	Left Front Fender	100.3	99	104	99
5	Left Front Door	104.8	100	100	115
6	Center Panel Left				
7	Left Rear Door	102.2	104	99	104
8	Left Back Panel	108.3	114	107	104
9	Right Front Fender	106.6	111	109	100
10	Right Front Door	100.0	100	100	100
11	Center Panel Right				
12	Right Rear Door	110.3	111	105	115
13	Right Back Panel	113.3	112	104	124

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Large / Rear Seat - Grime - Large / Rear Seat - Cigarette Burns - Burnt, Hole / Overall Interior - Smell - Yes / (L) Front Seat - Grime - Large / Rear Seat - Partially Missing - Yes / Trunk Room - Loose, Deformed - Large / Ceiling - Loose, Deformed - Large	Remarks Bonnet - Repair Traces - Yes / Rear End Panel - Repair Traces - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Rear Windshield - Damaged - Large / (R) Rear Fender, Molding - Crack, Gap - Large / (R) Rear Door, Molding - Crack, Gap - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / Roof Spoiler, Molding - Crack, Gap - Large
Frame Evaluation : D	Functional Evaluation : C
Remarks Rear Side Member & Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes / Under Spare Box - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes / Left Tyre House - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Tyre House - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Side Member & Trunk Room Floor - Condition of Welding, Hardness and Shape of Sealant ? - Yes	Remarks Warning Lamps - Issue - Yes / Door Lock - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
BSM AND RCTA warning light/ maintenance warning light/ tail light issue/ no warranty booklet/ no spare tire and jack/ no tools/ reverse camera issue/ rear door issue/ rear sensor issue/ with LTO plate/