

General Information

Date & Time: 05, Jan, 2026 16:20

Make	Toyota	Model	Avanza
YOM	2008	Odo Meter Reading	82,953
Registration No.	ZPG940	Chassis No.	MHFM1BE2F7K007149
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	416.6	419	416	415
2	Boot Lid	195.3	167	241	178
3	Roof	148.0	128	127	154/183
4	Left Front Fender	175.3	196	169	161
5	Left Front Door	153.0	158	158	143
6	Center Panel Left				
7	Left Rear Door	168.6	172	166	168
8	Left Back Panel	173.3	184	169	167
9	Right Front Fender	192.0	191	207	178
10	Right Front Door	304.6	255	432	227
11	Center Panel Right				
12	Right Rear Door	287.6	207	317	339
13	Right Back Panel	201.3	171	199	234

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / Dashboard - Worked - Minimal / Ceiling - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Console, Switchs, Vents - Worked - Minimal / Rear Seat - Grime - Small / Rear Seat Head Rest - Worked - Small / Trunk Room - Worked - Minimal / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (R) Rear Trim - Worked - Small / (L) Rear Trim - Grime - Small / Overall Interior - Worn as per age - Yes</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Roof - Repair mark - Yes / Overall Exterior - Full Re-Paint in same color - Yes / Bonnet, Headlight - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : D	Functional Evaluation : C
<p>Remarks Right Front Pillar - Condition of Welding ? - Yes / Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes / Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Center Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Side Member & Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes

with LTO plate, with spare tire, no warranty & manual booklet, no tools & jack, no spare key, no reverse camera, scratches on tailight and headlight, aircon issue.