

## General Information

Date & Time: 06, Jan, 2026 08:36

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	39,925
<b>Registration No.</b>	NIA7893	<b>Chassis No.</b>	PA1B18F32P4229339
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Green		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	149.3	154	160	134
2	Boot Lid	120.7	94	164	104
3	Roof	95.6	98	98	91/96
4	Left Front Fender	103.3	102	106	102
5	Left Front Door	120.3	123	115	123
6	Center Panel Left				
7	Left Rear Door	153.6	162	144	155
8	Left Back Panel	222.3	184	315	168
9	Right Front Fender	172.6	166	177	175
10	Right Front Door	121.6	125	120	120
11	Center Panel Right				
12	Right Rear Door	150.3	151	148	152
13	Right Back Panel	204.3	312	176	125

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Overall Interior - Smell - Yes / (L) Front Seat - Cigarette Burns - Burnt, Hole / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / Console, Switches, Vents - Traces of Adhesive Tape - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal / Ceiling - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Worn - Yes / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Repair mark - Yes / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Small / Roof - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	B
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
no warranty booklet, jack, tools and spare tire, with LTO plate, scratches on headlight and tail light, possible flooding, cracked tail light,