

## General Information

Date & Time: 10, Jan, 2026 19:00

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	32,837
<b>Registration No.</b>	NFS6323	<b>Chassis No.</b>	MR0BA3CD6P0194583
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	90	150	105
2	Boot Lid	158.6	87	144	245
3	Roof	145.2	134	145	166/136
4	Left Front Fender	164.3	140	154	199
5	Left Front Door	413.6	280	633	328
6	Center Panel Left				
7	Left Rear Door	302.0	218	305	383
8	Left Back Panel	403.0	616	222	371
9	Right Front Fender	171.6	183	168	164
10	Right Front Door	198.3	145	312	138
11	Center Panel Right				
12	Right Rear Door	148.3	140	157	148
13	Right Back Panel	169.0	202	152	153

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>C</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Floor Mat - Cut, Crack - Medium / (R) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Steering Wheel - Worn, Peel, Crack - Medium / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Dashboard - Repair Mark - Yes / Rear Seat - Grime - Small</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Overall Exterior - Full Re-Paint in same color - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Scratch &amp; Dent - Small / Bonnet, Headlight - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Guard Frame - Scratch &amp; Dent - Small / Rear Gate - Repair mark - Yes / Rear Gate - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Side Gate - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Cargo Bed Floor - Scratch - Medium / Roof - Scratch &amp; Dent - Small / Cab Back Panel - Scratch - Small</p>	
<b>Frame Evaluation :</b>	<b>D</b>	<b>Functional Evaluation :</b>	<b>D</b>
<p><b>Remarks</b> Right Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p><b>Remarks</b> Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

## Inspector Notes

with reverse camera, no LTO plate, no spare key, no spare tire, no tools & jack, no warranty and manual booklet, issue on tailight, check engine indicator, issue on aircon, issue on under chassis.