

## General Information

Date & Time: 29, Dec, 2025 18:49

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	24,330
<b>Registration No.</b>	BAG7907	<b>Chassis No.</b>	MR0JB8DD5R3554707
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	122	129	125
2	Boot Lid	92.3	93	89	94
3	Roof	120.0	116	112	117/135
4	Left Front Fender	117.0	123	114	114
5	Left Front Door	118.0	119	112	123
6	Center Panel Left				
7	Left Rear Door	106.4	117	104	98
8	Left Back Panel	121.6	117	123	125
9	Right Front Fender	111.6	111	110	114
10	Right Front Door	111.6	111	110	114
11	Center Panel Right				
12	Right Rear Door	102.9	92	101	116
13	Right Back Panel	113.0	113	115	111

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Minimal / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Rear Trim - Cut, Crack - Minimal / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Minimal</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Side Gate - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with warranty booklet, with spare tire, 1key, no jack and tools, scratches on headlight and taillight,</p>