

## General Information

Date & Time: 07, Jan, 2026 15:31

<b>Make</b>	Mitsubishi	<b>Model</b>	Strada
<b>YOM</b>	2018	<b>Odo Meter Reading</b>	74,439
<b>Registration No.</b>	NBE2108	<b>Chassis No.</b>	MMBJNKK30JH048602
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	108	102	105
2	Boot Lid	92.3	96	95	86
3	Roof	65.8	64	65	63/73
4	Left Front Fender	132.3	127	108	162
5	Left Front Door	99.3	105	99	94
6	Center Panel Left				
7	Left Rear Door	121.0	99	101	163
8	Left Back Panel	87.9	79	89	97
9	Right Front Fender	96.0	93	94	101
10	Right Front Door	95.7	93	97	97
11	Center Panel Right				
12	Right Rear Door	80.8	82	75	85
13	Right Back Panel	101.8	153	69	84

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Overall Interior - Worn as per age - Yes / (L) Front Seat - Worn - Yes / Ceiling - Grime - Medium / (R) Front Seat - Worn - Yes / Rear Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Dashboard - Traces of Adhesive Tape - Yes</p>	<p><b>Remarks</b> (R) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch &amp; Dent - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Small / (L) Center Panel - Scratch - Small / (L) Side Gate - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Air Conditioner - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet, jack and tools, with spare tire and LTO PLATE, scratches on headlight and tail light, suncrack headlights and tail light, yellowish headlight, plate light issue</p>