

## General Information

Date & Time: 13, Jan, 2026 15:20

|                         |         |                          |                   |
|-------------------------|---------|--------------------------|-------------------|
| <b>Make</b>             | Toyota  | <b>Model</b>             | Hiace             |
| <b>YOM</b>              | 2022    | <b>Odo Meter Reading</b> | 224,661           |
| <b>Registration No.</b> | GAW4107 | <b>Chassis No.</b>       | JTFNAFAP3M8023580 |
| <b>CC</b>               | 2.8     | <b>Transmission</b>      | M/T               |
| <b>Fuel Type</b>        | Diesel  | <b>Type of Body</b>      | Van               |
| <b>Colour</b>           | Black   |                          |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 117.6         | 117    | 107    | 129      |
| 2  | Boot Lid           | 148.0         | 151    | 152    | 141      |
| 3  | Roof               | 146.1         | 91     | 111    | 182/201  |
| 4  | Left Front Fender  | 144.0         | 150    | 147    | 135      |
| 5  | Left Front Door    | 143.6         | 149    | 140    | 142      |
| 6  | Center Panel Left  | 165.0         | 151    | 182    | 162      |
| 7  | Left Rear Door     |               |        |        |          |
| 8  | Left Back Panel    | 149.6         | 130    | 153    | 166      |
| 9  | Right Front Fender | 165.6         | 164    | 169    | 164      |
| 10 | Right Front Door   | 146.0         | 156    | 149    | 133      |
| 11 | Center Panel Right | 154.6         | 139    | 168    | 157      |
| 12 | Right Rear Door    | 156.0         | 151    | 155    | 162      |
| 13 | Right Back Panel   | 165.6         | 160    | 163    | 174      |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

|   |  |
|---|--|
| <b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>  | <b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>   |
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>  |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>  |
| <p><b>Remarks</b><br/>(R) Front Seat - Grime - Small / Console, Switches, Vents - Traces of Adhesive Tape - Yes / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Large / Rear Seat - Cigarette Burns - Burnt Minimal / Ceiling - Grime - Large / Steering Wheel - Worn, Peel, Crack - Large / (L) Front Seat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / Overall Interior - Worn as per age - Yes</p> | <p><b>Remarks</b><br/>Overall Exterior - Faded(Color, Gloss) - Yes / (L) Front Fender, Molding - Scratch &amp; Dent - Large / (L) Mirror - Scratch - Medium / (L) Front Door, Molding - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Large / Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Center Panel - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Mirror - Scratch - Medium / (R) Front Fender, Molding - Scratch &amp; Dent - Medium / Front Bumper, Grille, Lamps - Modified - Large / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small / Front Windshield - Damaged - Large</p> |
| <b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>   | <b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>   |
| <p><b>Remarks</b><br/>Defects not found</p>   | <p><b>Remarks</b><br/>Retractable Mirror - Issue - Yes / Power Steering - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Spare Key - Issue - Unexist</p>   |

|   |
|---|
| <p><b>Inspector Notes</b></p>   |
| <p>Possible flooding. Battery for replacement. Engine oil for replacement. Abnormal vibration at engine. Crack both tail lights. Left side mirror issue. Crack Front windshield. Radio issue. Without warranty booklet, jack, tools and seat cover. With spare tire. 1 key. No LTO plate.</p> |