

## General Information

Date & Time: 09, Jan, 2026 15:53

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2017	<b>Odo Meter Reading</b>	101,246
<b>Registration No.</b>	NBX6365	<b>Chassis No.</b>	PAEA13TJHHA000416
<b>CC</b>	1.2	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	104	105	110
2	Boot Lid	108.3	107	109	109
3	Roof	97.2	95	99	88/107
4	Left Front Fender	111.6	123	100	112
5	Left Front Door	99.2	99	99	99
6	Center Panel Left				
7	Left Rear Door	106.3	108	103	108
8	Left Back Panel	109.5	125	110	94
9	Right Front Fender	112.0	115	107	114
10	Right Front Door	110.6	115	109	108
11	Center Panel Right				
12	Right Rear Door	111.0	112	105	116
13	Right Back Panel	107.0	90	105	126

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	E
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Sunvisor, Sunglass Holder - Grime - Medium / Trunk Room - Loose, Deformed - Large</p>		<p><b>Remarks</b> Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch &amp; Dent - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Medium / Roof - Scratch - Medium</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	B
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Door Lock - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Lto plate, with spare and jack, no warranty booklet and tools, 1key, scratches on headlights and cracked taillight, issue on radio