

## General Information

Date & Time: 12, Jan, 2026 11:29

<b>Make</b>	Mitsubishi	<b>Model</b>	Adventure
<b>YOM</b>	2017	<b>Odo Meter Reading</b>	88,041
<b>Registration No.</b>	NAO5457	<b>Chassis No.</b>	PAEVB5NMHHB012829
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	558.3	874	640	161
2	Boot Lid	525.6	553	660	364
3	Roof	71.2	58	46	97/84
4	Left Front Fender	501.0	1,016	299	188
5	Left Front Door	115.6	110	108	129
6	Center Panel Left				
7	Left Rear Door	322.6	143	113	712
8	Left Back Panel	196.3	168	153	268
9	Right Front Fender	449.3	180	208	960
10	Right Front Door	121.3	123	113	128
11	Center Panel Right				
12	Right Rear Door	354.0	140	143	779
13	Right Back Panel	138.6	139	127	150

**Overall Evaluation :**

B

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>C</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Ceiling - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small / Rear Seat - Cut, Crack - Small / Carpet - Worn, Scratch, Cut, Crack - Medium / Room Lamp - Stuck - Yes</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Overall Exterior - Full Re-Paint in same color - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Crack, Gap - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Door Lock - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Lto plate, with spare tire, 1key, no warranty booklet, no jack and tools, unusual sound on engine, parking brake light malfunction, scratches on headlights and taillights