

## General Information

Date & Time: 12, Jan, 2026 11:28

<b>Make</b>	Hyundai	<b>Model</b>	H100
<b>YOM</b>	2020	<b>Odo Meter Reading</b>	135,372
<b>Registration No.</b>	NGD8664	<b>Chassis No.</b>	KMFZBX7KALU759919
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Shuttle
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	410.0	118	1,004	108
2	Boot Lid	86.4	96	82	81
3	Roof	75.4	73	73	73/83
4	Left Front Fender	365.3	105	172	819
5	Left Front Door	83.5	82	75	94
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	175.6	196	142	189
9	Right Front Fender	304.8	181	639	94
10	Right Front Door	277.2	84	91	657
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	505.5	248	99	1,170

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Overall Interior - Worn as per age - Yes / Ceiling - Loose, Deformed - Large / Knobs - Worn, Peel, Crack - Small / (R) Front Seat - Cut, Crack - Minimal</p>	<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Center Panel - Scratch &amp; Dent - Small / (R) Side Gate - Scratch &amp; Dent - Large / Overall Exterior - Full Re-Paint in same color - Yes / (R) Side Gate - Repair mark - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Rear Gate - Rust, Corrosion - Medium / (L) Side Gate - Repair mark - Difference in Color / (L) Side Gate - Scratch &amp; Dent - Large / (L) Center Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Minimal / (L) Mirror - Crack - Damaged / Front Bumper, Grille, Lamps - Crack, Gap - Large / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Scratch &amp; Dent - Minimal / Bonnet, Headlight - Repair mark - Yes / Roof - Repair mark - Yes</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Front Cross Member Support - Condition of Welding ? - Yes / Right Front Inside Panel (Front Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes / Right Front Inside (Rear Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes</p>	<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with spare tire and jack, 1key, no warranty booklet, no tools, scratches on headlights, Crack taillight,</p>