

General Information

Date & Time: 15, Jan, 2026 05:42

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	28,456
Registration No.	DAV9831	Chassis No.	MHKA4DF5FMJ059167
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.0	144	126	123
2	Boot Lid	118.3	112	125	118
3	Roof	81.1	68	86	90/80
4	Left Front Fender	119.0	95	122	140
5	Left Front Door	432.6	730	167	401
6	Center Panel Left				
7	Left Rear Door	357.3	481	440	151
8	Left Back Panel	598.6	728	962	106
9	Right Front Fender	94.1	89	99	94
10	Right Front Door	94.2	91	99	94
11	Center Panel Right				
12	Right Rear Door	103.2	97	96	117
13	Right Back Panel	93.2	95	93	92

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	E	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Rear Trim - Grime - Medium / Ceiling - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Large / (R) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Large</p>		<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Rust, Corrosion - Large / Roof - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate/with spare tire/No spare key/with jack and incomplete tools/No warranty booklet/No reverse camera/interior dirty/possible flooding//with check engine /rear view mirror missing/aircon issue