

General Information

Date & Time: 15, Jan, 2026 10:20

Make	Mitsubishi	Model	Mirage
YOM	2023	Odo Meter Reading	46,115
Registration No.	DAS9721	Chassis No.	PAEA13MJPNA015108
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	151.6	142	162	151
2	Boot Lid	107.0	103	105	113
3	Roof	101.5	104	95	103/104
4	Left Front Fender	159.3	162	157	159
5	Left Front Door	173.3	201	163	156
6	Center Panel Left				
7	Left Rear Door	148.3	165	143	137
8	Left Back Panel	181.3	209	179	156
9	Right Front Fender	161.3	164	153	167
10	Right Front Door	113.3	116	111	113
11	Center Panel Right				
12	Right Rear Door	107.3	102	108	112
13	Right Back Panel	117.6	107	118	128

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Large / Mat Other - Grime - Large / Ceiling - Grime - Small / (R) Front Seat - Grime - Large</p>	<p>Remarks (R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Overall Exterior - Faded(Color, Gloss) - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes</p>
Frame Evaluation : B	Functional Evaluation : D
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Gap at front bumper and bonnet. Aircon fan issue. Maintenance warning lamp. Possible flooding. front bumper lower right partially missing. Without warranty booklet, tools and seat cover. With spare tire and jack. 1 key. No LTO plate. With temporary plate.</p>