

## General Information

Date & Time: 19, Jan, 2026 13:15

<b>Make</b>	Nissan	<b>Model</b>	Navara
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	40,260
<b>Registration No.</b>	NFS6704	<b>Chassis No.</b>	MNTCCAD23Z0021233
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	113	101	108
2	Boot Lid	98.2	95	100	100
3	Roof	92.3	90	100	82/98
4	Left Front Fender	103.2	105	108	97
5	Left Front Door	88.3	97	89	79
6	Center Panel Left				
7	Left Rear Door	91.2	93	92	89
8	Left Back Panel	95.6	91	100	96
9	Right Front Fender	100.2	96	99	105
10	Right Front Door	94.5	90	95	99
11	Center Panel Right				
12	Right Rear Door	89.3	90	96	82
13	Right Back Panel	107.9	106	94	124

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Medium / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> (L) Front Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Side Gate - Scratch &amp; Dent - Large / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Side Gate - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small / Roof - Repair mark - Yes</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Panel, Meter - Issue - Yes / Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>Instrument panel display issue. Reverse camera issue. Aircon at second row center panel blower issue. Without warranty booklet, tools and seat cover. With spare tire and jack. 2 keys. With LTO plate.</p>