

General Information

Date & Time: 16, Jan, 2026 10:34

Make	Suzuki	Model	Carry
YOM	2022	Odo Meter Reading	34,097
Registration No.	NIB7474	Chassis No.	MHYHDC01MI916235
CC	1.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	125	108	130
2	Boot Lid	114.9	76	43	226
3	Roof	99.4	108	106	97/86
4	Left Front Fender	128.0	135	131	118
5	Left Front Door	94.5	100	97	86
6	Center Panel Left	107.7	116	108	99
7	Left Rear Door				
8	Left Back Panel	137.3	167	127	118
9	Right Front Fender	114.6	117	114	113
10	Right Front Door	96.7	93	101	96
11	Center Panel Right	104.5	108	111	95
12	Right Rear Door				
13	Right Back Panel	209.0	204	200	223

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / Overall Interior - Worn as per age - Yes / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Large / (L) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / Rear Gate - Rust, Corrosion - Medium / (L) Center Panel - Scratch - Minimal / Front Panel - Scratch - Small / Roof - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no warranty Booklet, Jack, and Tools, with Sparetire and LTO Plate, Scratches on Tail light</p>