

General Information

Date & Time: 20, Jan, 2026 10:20

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	35,840
Registration No.	NEP7352	Chassis No.	MHKA4DF5FMJ052179
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	145.3	145	150	141
2	Boot Lid	155.0	156	151	158
3	Roof	76.3	66	89	76/75
4	Left Front Fender	181.0	176	183	184
5	Left Front Door	181.6	187	176	182
6	Center Panel Left				
7	Left Rear Door	135.3	141	128	137
8	Left Back Panel	156.6	181	150	139
9	Right Front Fender	210.3	192	207	232
10	Right Front Door	133.3	141	131	128
11	Center Panel Right				
12	Right Rear Door	137.0	149	124	138
13	Right Back Panel	138.0	144	139	131

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Crinkle - Medium / (R) Front Trim - Cut, Crack - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Dent - Small / (L) Rear Fender, Molding - Dent - Minimal / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
no warranty booklet, no jack, with tools, with spare tire, with LTO plate, scratched and cracked tail light